



POSITION CLAMP PLATE ONTO WORK SURFACE



CONFIGURE FOR WORKSURFACE THICKNESS






Use a 4mm Allen Key

A IMPO
Ensure scri

FIT CLAMP SCREWS

ONDO TOP MOUNT CLAMP

UNI/TAC/OND








18-25mm surface thickness

FIT C-BRACKET




⚠ IMPORTANT NOTE


Ensure inside of bracket is flush against back of work surface

FOLD

FIT SPACER TO CLAMP



FIT ONDO AND WISHBONE POST



△ WARNING

- Do not use this product for any purpose other than that for which it was designed
- Ensure desk/worksurface is suitable to take the weight of the arm/s and monitors
- Supported weight must not exceed the maxium load per arm
- Take care when installing as fingers could become trapped

- Ensure all screws are tightened and occasionally adjust if needed
- Ensure arm is pushed fully down onto the clamp before installing the monitor(s)
- Clean with a damp cloth, NO solvents

A DISCLAIMERS

- The use of power tools, lever bars or excessive force during the installation, or re-configuration of the product will invalidate your guarantee
- Failure to observe the recommendations in the use, and configuration of these products may affect your guarantee
- As a part of Colebrook Bosson Saunders ongoing product improvement programme the design of products may change without prior notice and details may vary from those illustrated

PATENTS

Colebrook Bosson Saunders hold a number of patents and other intellectual property rights covering our products and processes. You can find patent information on our website at:

www.colebrookbossonsaunders.com/patents

Please consider leaving these instructions with the product if further installation may be required by others

UNI-TAC-OND-INST-A-JUN-2022



| FOLD | FOLD | Print size - A4 | 297mm x 210mm